

Landscaping does not obstruct visibility between street and front/rear entryway(s)

Documented annual review of fire evacuation and other emergency procedures

Smoke alarms are installed in every bedroom and all are operating properly

Smoke alarms are interconnected (wired or wireless) and operate properly

Building emergency evacuation plans complete and clearly posted, or exit signs installed above exits

Security system with off-site monitoring and reporting capabilities available for tenant activation

Property is lighted at exterior entry/exits, walkways and parking areas

Exterior doors and frames are in good condition and properly installed

Exterior doors are equipped with working deadbolts



	Buckeye	Excellence	Level
--	---------	------------	-------

6.

7.

8.

9.

10.

11.

12.

13.

14.

5 buckeyes

 \leq

 $\overline{\mathbf{x}}$

 \leq

 \leq

 \checkmark

 \mathbf{Z}

 $\overline{\mathbf{x}}$

					1	green bu	cheye
Date:	1/26/2018	Time In:	10:00 AM	Time Out:	10:30 AM		
Addre	ess: 1637 North Fourth Street , Columb	us, 43201	Program N	lanager: Amanda Waples			
sign b	nents: Fire safety tip- remind students t reside escape ladders so students don't how students how to open/remove Wind	remove; send pics or video					
Pr	e-Requisites						
All pre-	requisites must be met to participate in	the Off-Campus Housing E	xcellence Program and ear	rn credits toward buckeyes.			
1.	Date of signed acknowledgement that p	property meets City of Colur	mbus Housing Code		7	7/1/2016	
2.	Date of fire safety check by City of Colu	mbus Division of Fire			1	1/26/2018	Y
3.	Date of Home Visit by Student Life's Of	f-Campus Housing Exellend	ce Program Coordinator		1	1/26/2018	₹
Cr	edits						
	yes are awarded based on the percentage of the percentage otal score, while operations & sustainab	•	•	ncrements. The categories are we	eighted. Safety & F	Physical Secui	rity is 60%
Saf	fety & Physical Security				60%	of Total	Score
Reg	gular Credits		If a credit listed	below is not applicable to the p	property it is not o	counted agai	nst score
1.	Off-site emergency contact number fo	r fire and other emergencie	s (available 24/7/365)				丞
2.	Tenant has life safety training						
3.	Tenant(s) provided with personal secu	rity and fire prevention info	rmation				\mathbf{Y}
4.	Keyless door access to rental unit						
5.	Street address is clearly marked and	visible from front and rear (i	f alley access); minimum 4	" height			Y
6	Landscaping does not obstruct visibili	v between street and front/	rear entryway(s)				₹

15.	Smoke alarms are connected to off-site monitoring and reporting system	
16.	Carbon Monoxide detector installed and operating properly in each sleeping area	
17.	At least one fire extinguisher provided at tenant's request (properly tagged and inspected annually)	
18.	Emergency escape ladders or permanent exit provided for bedrooms above ground floor	
19.	No combustible materials are stored indoors or near heating or ignition sources	丞
Во	nus Credits These do not count against score, but up to 4 can be used to l	boost the score
20.	Resident completed SAFE@Home safety course	n/a 🔲
21.	Keyless access for building entry	
22.	Battery operated door alarms on all exterior doors	
23.	Sprinkler system installed, tagged and properly maintained (partial or full coverage)	
24.	Kitchen hood suppression system or cooking fire prevention technology installed in kitchen/range	
25.	Battery operated window alarms on all accessible windows	
26.	If security bars are installed on lower level windows, security bars are break-away style	n/a
27.	Fire alarm system with manual pull stations and emergency strobes	
28.	Operational security camera system at all entry/exit points	
29.	Operational security camera system monitors tenant parking area	
30.	Carbon Monoxide detector installed and operating properly on every floor (not within 15' of gas appliances)	
31.	At least one fire extinguisher on every floor, regardless of tenant request (tagged and inspected annually)	
32.	At least one entry/exit is wheelchair accessible	
		□ 「otal Score
Ор		Total Score
Ор	perations & Sustainability 40% of 1	Total Score
Op	perations & Sustainability gular Credits If a credit listed below is not applicable to the property it is not countered.	Total Score
Op Reg	perations & Sustainability gular Credits If a credit listed below is not applicable to the property it is not counter Maintenance request system available 24/7/365	Total Score d against score
Op Res 1. 2.	perations & Sustainability gular Credits If a credit listed below is not applicable to the property it is not counter Maintenance request system available 24/7/365 Web-based service request system	Total Score d against score
1. 2. 3.	perations & Sustainability gular Credits If a credit listed below is not applicable to the property it is not counter Maintenance request system available 24/7/365 Web-based service request system Confirmation of service request made to tenant within 48 hours	Total Score d against score
1. 2. 3. 4.	perations & Sustainability gular Credits If a credit listed below is not applicable to the property it is not counter Maintenance request system available 24/7/365 Web-based service request system Confirmation of service request made to tenant within 48 hours Confirmation of service request made to tenant within 24 hours	Total Score d against score
1. 2. 3. 4. 5.	perations & Sustainability gular Credits If a credit listed below is not applicable to the property it is not counter Maintenance request system available 24/7/365 Web-based service request system Confirmation of service request made to tenant within 48 hours Confirmation of service request made to tenant within 24 hours Annual HVAC equipment maintenance by certified technician	Total Score d against score
1. 2. 3. 4. 5. 6.	perations & Sustainability gular Credits If a credit listed below is not applicable to the property it is not counter Maintenance request system available 24/7/365 Web-based service request system Confirmation of service request made to tenant within 48 hours Confirmation of service request made to tenant within 24 hours Annual HVAC equipment maintenance by certified technician Process for addressing pests is established	Total Score d against score
1. 2. 3. 4. 5. 6. 7.	gular Credits If a credit listed below is not applicable to the property it is not counter Maintenance request system available 24/7/365 Web-based service request system Confirmation of service request made to tenant within 48 hours Confirmation of service request made to tenant within 24 hours Annual HVAC equipment maintenance by certified technician Process for addressing pests is established Property and building free of graffiti	Total Score d against score
1. 2. 3. 4. 5. 6. 7. 8.	perations & Sustainability gular Credits If a credit listed below is not applicable to the property it is not counter Maintenance request system available 24/7/365 Web-based service request system Confirmation of service request made to tenant within 48 hours Confirmation of service request made to tenant within 24 hours Annual HVAC equipment maintenance by certified technician Process for addressing pests is established Property and building free of graffiti Property and exterior of building in good repair	Total Score d against score
1. 2. 3. 4. 5. 6. 7. 8. 9.	perations & Sustainability gular Credits If a credit listed below is not applicable to the property it is not counter Maintenance request system available 24/7/365 Web-based service request system Confirmation of service request made to tenant within 48 hours Confirmation of service request made to tenant within 24 hours Annual HVAC equipment maintenance by certified technician Process for addressing pests is established Property and building free of graffiti Property and exterior of building in good repair Property is free of trash, with regularly scheduled pickup	Total Score d against score
1. 2. 3. 4. 5. 6. 7. 8. 9. 10.	perations & Sustainability gular Credits If a credit listed below is not applicable to the property it is not counted Maintenance request system available 24/7/365 Web-based service request made to tenant within 48 hours Confirmation of service request made to tenant within 24 hours Annual HVAC equipment maintenance by certified technician Process for addressing pests is established Property and building free of graffiti Property and exterior of building in good repair Property is free of trash, with regularly scheduled pickup On-site recycling provided to tenant(s)	Total Score d against score
1. 2. 3. 4. 5. 6. 7. 8. 9. 10. 11.	perations & Sustainability gular Credits If a credit listed below is not applicable to the property it is not counted. Maintenance request system available 24/7/365 Web-based service request system Confirmation of service request made to tenant within 48 hours Confirmation of service request made to tenant within 24 hours Annual HVAC equipment maintenance by certified technician Process for addressing pests is established Property and building free of graffiti Property and exterior of building in good repair Property is free of trash, with regularly scheduled pickup On-site recycling provided to tenant(s) Building interior is maintained in good repair	Total Score d against score
1. 2. 3. 4. 5. 6. 7. 8. 9. 10. 11. 12.	perations & Sustainability gular Credits If a credit listed below is not applicable to the property it is not counter Maintenance request system available 24/7/365 Web-based service request system Confirmation of service request made to tenant within 48 hours Confirmation of service request made to tenant within 24 hours Annual HVAC equipment maintenance by certified technician Process for addressing pests is established Property and building free of graffiti Property and exterior of building in good repair Property is free of trash, with regularly scheduled pickup On-site recycling provided to tenant(s) Building interior is maintained in good repair Electrical system updated to include polarized, grounded receptacles	Total Score d against score

16.	Double pane glass windows installe	ed, or residents provided with plastic to cover windows	S	
17.	. Bike racks on property			
Bor	Bonus Credits These do not count against score, but up to 4 can be used to boost the score			
18.	Insulated exterior sidewalls and/or att	rtic		
19.	At least 90% Efficient Furnace		丞	
20.	Additional exterior lighting on motion	sensors beyond entry/exit points	丞	
21.	Low flow, aerating shower heads and	d faucets are installed in bathroom(s) and kitchen	丞	
22.	Provided range and washer are Ener	rgy Star Rated; oven is self-cleaning	丞	
23.	Storm windows installed and present	t (at least December through February)		
24.	Compact Fluorescent Light bulbs ins	stalled for all interior fixtures that use standard screw-based lamps		
25.	Bedroom, bathroom, kitchen, and livi	ing room light fixtures hardwired to use energy efficient technology		
26.	Indoor bike rack storage			
То	tal Weighted Score		100%	
То	tal Buckeyes Earned	Buckeyes are awarded based on the percentage of credits received, earning half buckeyes in 10% increments. The categories are weighted. Safety & Physical Security is 60% of the total score, while operations & sustainability is 40% of the total score.	5	
Gr	reen Buckeye Earned	The Green Buckeye is earned if a property receives at least 50% of the applicable green criteria (highlighted by a green accent) that directly relate to "green" living.	Yes	

The Off-Campus Housing Excellence Program provides safety, security, operations, and sustainability information and education to students of The Ohio State University. The program informs individuals of potential risks and hazards; the program does not eliminate risks and hazards. The housing assessment results provided herein are for informational purposes only. The assessment results are a snapshot reflecting the day and time the housing was visited by University representatives. The condition or status of a property may change at any time. Neither The Ohio State University nor its employees make any representations, warranties or guarantees regarding the safety, suitability, adequacy, performance or condition, security, operations, or environmental sustainability of housing visited through the Off-Campus Housing Excellence Program. The Ohio State University expressly disclaims any and all responsibility for any problems that may arise with regard to such off-campus housing. All prospective tenants are encouraged to exercise their own good judgment when evaluating prospective rental units and landlords.