

Smoke alarms are interconnected (wired or wireless) and operate properly



Buckeye	Excellence	Level
---------	------------	-------

5 buckeyes

Dat	cheye Excellence Level					n buckeye
Date:	1/26/2018	Time In:	10:30 AM	Time Out:	11:00 AM	
	ess: 1645 North 4th Street , Columbus, 43201	·	_	Manager: Amanda Waples		
in bed	nents: Cleared boxes 3' from furnace No power room 1, 6, 8 smoke alarm Coffee maker on extesion cords		•			
Pro	e-Requisites					
All pre-	requisites must be met to participate in the Off-C	Campus Housing	Excellence Program and ea	arn credits toward buckeyes.		
1.	Date of signed acknowledgement that property	meets City of Col	umbus Housing Code		7/1/2016	5 <b></b>
2.	Date of fire safety check by City of Columbus D	ivision of Fire			1/26/20	18 🗹
3.	Date of Home Visit by Student Life's Off-Campu	ıs Housing Exelle	nce Program Coordinator		1/26/201	18 🗹
Cr	edits					
•	res are awarded based on the percentage of creotal score, while operations & sustainability is 40		•	increments. The categories are v	weighted. Safety & Physical	Security is 60%
Saf	Safety & Physical Security 60% of Total Score					
Reg	ular Credits		If a credit listed	d below is not applicable to the	property it is not counted	d against score
1.	Off-site emergency contact number for fire and	d other emergenci	es (available 24/7/365)			<b></b>
2.	Tenant has life safety training					<b></b>
3.	Tenant(s) provided with personal security and	fire prevention inf	ormation			<b></b>
4.	Keyless door access to rental unit					
5.	Street address is clearly marked and visible from	om front and rear	(if alley access); minimum	4" height		<b></b>
6.	Landscaping does not obstruct visibility between	en street and fron	t/rear entryway(s)			<b></b>
7.	Property is lighted at exterior entry/exits, walks	ways and parking	areas			<b></b>
8.	Exterior doors and frames are in good condition	on and properly in	stalled			₹
9.	Exterior doors are equipped with working dead	dbolts				丞
10.	Documented annual review of fire evacuation	and other emerge	ncy procedures			<b></b>
11.	Building emergency evacuation plans complet	e and clearly post	ed, or exit signs installed a	above exits		<b></b>
12.	Security system with off-site monitoring and re	porting capabilitie	es available for tenant activ	ation		
13.	Smoke alarms are installed in every bedroom	and all are operat	ing properly			₹

15.	. Smoke alarms are connected to off-site monitoring and reporting system		
16.	Carbon Monoxide detector installed and operating properly in each sleeping area	<b></b>	
17.	At least one fire extinguisher provided at tenant's request (properly tagged and inspected annually)	<b></b>	
18.	Emergency escape ladders or permanent exit provided for bedrooms above ground floor	<b></b>	
19.	No combustible materials are stored indoors or near heating or ignition sources	₹	
Во	nus Credits  These do not count against score, but up to 4 can be used to	boost the score	
20.	Resident completed SAFE@Home safety course	n/a	
21.	Keyless access for building entry		
22.	Battery operated door alarms on all exterior doors	<b></b>	
23.	Sprinkler system installed, tagged and properly maintained (partial or full coverage)		
24.	Kitchen hood suppression system or cooking fire prevention technology installed in kitchen/range		
25.	Battery operated window alarms on all accessible windows	<b></b>	
26.	If security bars are installed on lower level windows, security bars are break-away style	n/a	
27.	Fire alarm system with manual pull stations and emergency strobes		
28.	Operational security camera system at all entry/exit points		
29.	Operational security camera system monitors tenant parking area		
30.	Carbon Monoxide detector installed and operating properly on every floor (not within 15' of gas appliances)	<b></b>	
31.	At least one fire extinguisher on every floor, regardless of tenant request (tagged and inspected annually)	<b></b>	
32.	At least one entry/exit is wheelchair accessible		
	·	□ Fotal Score	
Ор	·	Total Score	
Ор	perations & Sustainability 40% of	Total Score	
Op	perations & Sustainability  gular Credits  If a credit listed below is not applicable to the property it is not counter.	Total Score	
Op Reg	perations & Sustainability  gular Credits  If a credit listed below is not applicable to the property it is not counte  Maintenance request system available 24/7/365	Total Score d against score	
Op Res	perations & Sustainability  gular Credits  If a credit listed below is not applicable to the property it is not counte  Maintenance request system available 24/7/365  Web-based service request system	Total Score d against score	
1. 2. 3.	perations & Sustainability  gular Credits  If a credit listed below is not applicable to the property it is not counted  Maintenance request system available 24/7/365  Web-based service request system  Confirmation of service request made to tenant within 48 hours	Total Score d against score	
1. 2. 3. 4.	perations & Sustainability  gular Credits  If a credit listed below is not applicable to the property it is not counted  Maintenance request system available 24/7/365  Web-based service request system  Confirmation of service request made to tenant within 48 hours  Confirmation of service request made to tenant within 24 hours	Total Score d against score	
1. 2. 3. 4. 5.	perations & Sustainability  gular Credits  If a credit listed below is not applicable to the property it is not counter  Maintenance request system available 24/7/365  Web-based service request system  Confirmation of service request made to tenant within 48 hours  Confirmation of service request made to tenant within 24 hours  Annual HVAC equipment maintenance by certified technician	Total Score d against score	
1. 2. 3. 4. 5. 6.	perations & Sustainability  gular Credits  If a credit listed below is not applicable to the property it is not counted.  Maintenance request system available 24/7/365  Web-based service request system  Confirmation of service request made to tenant within 48 hours  Confirmation of service request made to tenant within 24 hours  Annual HVAC equipment maintenance by certified technician  Process for addressing pests is established	Total Score d against score	
1. 2. 3. 4. 5. 6. 7.	gular Credits  If a credit listed below is not applicable to the property it is not counted.  Maintenance request system available 24/7/365  Web-based service request system  Confirmation of service request made to tenant within 48 hours  Confirmation of service request made to tenant within 24 hours  Annual HVAC equipment maintenance by certified technician  Process for addressing pests is established  Property and building free of graffiti	Total Score d against score	
1. 2. 3. 4. 5. 6. 7. 8.	perations & Sustainability  gular Credits  If a credit listed below is not applicable to the property it is not counted.  Maintenance request system available 24/7/365  Web-based service request system  Confirmation of service request made to tenant within 48 hours  Confirmation of service request made to tenant within 24 hours  Annual HVAC equipment maintenance by certified technician  Process for addressing pests is established  Property and building free of graffiti  Property and exterior of building in good repair	Total Score d against score	
1. 2. 3. 4. 5. 6. 7. 8. 9.	perations & Sustainability  gular Credits  If a credit listed below is not applicable to the property it is not counted.  Maintenance request system available 24/7/365  Web-based service request system  Confirmation of service request made to tenant within 48 hours  Confirmation of service request made to tenant within 24 hours  Annual HVAC equipment maintenance by certified technician  Process for addressing pests is established  Property and building free of graffiti  Property and exterior of building in good repair  Property is free of trash, with regularly scheduled pickup	Total Score d against score	
1. 2. 3. 4. 5. 6. 7. 8. 9. 10.	perations & Sustainability  gular Credits  If a credit listed below is not applicable to the property it is not counted.  Maintenance request system available 24/7/365  Web-based service request made to tenant within 48 hours  Confirmation of service request made to tenant within 24 hours  Annual HVAC equipment maintenance by certified technician  Process for addressing pests is established  Property and building free of graffiti  Property and exterior of building in good repair  Property is free of trash, with regularly scheduled pickup  On-site recycling provided to tenant(s)	Total Score d against score	
1. 2. 3. 4. 5. 6. 7. 8. 9. 10. 11.	perations & Sustainability  gular Credits  If a credit listed below is not applicable to the property it is not counted.  Maintenance request system available 24/7/365  Web-based service request system  Confirmation of service request made to tenant within 48 hours  Confirmation of service request made to tenant within 24 hours  Annual HVAC equipment maintenance by certified technician  Process for addressing pests is established  Property and building free of graffiti  Property and exterior of building in good repair  Property is free of trash, with regularly scheduled pickup  On-site recycling provided to tenant(s)  Building interior is maintained in good repair	Total Score d against score	
1. 2. 3. 4. 5. 6. 7. 8. 9. 10. 11. 12.	perations & Sustainability  gular Credits  If a credit listed below is not applicable to the property it is not counted.  Maintenance request system available 24/7/365  Web-based service request system  Confirmation of service request made to tenant within 48 hours  Confirmation of service request made to tenant within 24 hours  Annual HVAC equipment maintenance by certified technician  Process for addressing pests is established  Property and building free of graffiti  Property and exterior of building in good repair  Property is free of trash, with regularly scheduled pickup  On-site recycling provided to tenant(s)  Building interior is maintained in good repair  Electrical system updated to include polarized, grounded receptacles	Total Score d against score	

16.	Double pane glass windows installe	ed, or residents provided with plastic to cover windows	<b></b>	
17.	Bike racks on property		<b></b>	
Bor	Bonus Credits  These do not count against score, but up to 4 can be used to boost the score			
18.	Insulated exterior sidewalls and/or at	ttic	<b></b>	
19.	At least 90% Efficient Furnace		<b></b>	
20.	Additional exterior lighting on motion	sensors beyond entry/exit points	<b></b>	
21.	Low flow, aerating shower heads and	d faucets are installed in bathroom(s) and kitchen	丞	
22.	Provided range and washer are Ener	rgy Star Rated; oven is self-cleaning	丞	
23.	Storm windows installed and present	t (at least December through February)	<b></b>	
24.	Compact Fluorescent Light bulbs ins	stalled for all interior fixtures that use standard screw-based lamps	<b></b>	
25.	Bedroom, bathroom, kitchen, and livi	ing room light fixtures hardwired to use energy efficient technology	<b></b>	
26.	Indoor bike rack storage			
То	tal Weighted Score		100%	
То	tal Buckeyes Earned	Buckeyes are awarded based on the percentage of credits received, earning half buckeyes in 10% increments. The categories are weighted. Safety & Physical Security is 60% of the total score, while operations & sustainability is 40% of the total score.	5	
Gr	reen Buckeye Earned	The Green Buckeye is earned if a property receives at least 50% of the applicable green criteria (highlighted by a green accent) that directly relate to "green" living.	Yes	

The Off-Campus Housing Excellence Program provides safety, security, operations, and sustainability information and education to students of The Ohio State University. The program informs individuals of potential risks and hazards; the program does not eliminate risks and hazards. The housing assessment results provided herein are for informational purposes only. The assessment results are a snapshot reflecting the day and time the housing was visited by University representatives. The condition or status of a property may change at any time. Neither The Ohio State University nor its employees make any representations, warranties or guarantees regarding the safety, suitability, adequacy, performance or condition, security, operations, or environmental sustainability of housing visited through the Off-Campus Housing Excellence Program. The Ohio State University expressly disclaims any and all responsibility for any problems that may arise with regard to such off-campus housing. All prospective tenants are encouraged to exercise their own good judgment when evaluating prospective rental units and landlords.